


light + motion surface installation instruction




Step 1




Turn the power off.

Step 2




Fix the mounting plate on the ceiling with appropriate screws.

Step 3




Tighten the wires through the strain relief and cut off the excess wire.

Step 4



Connect the wires with the wago connectors for parallel connection, respect polarity combine with a prado LED-driver.


Step 5



Standard settings:
 – Ambient light: 1700 LSB
 – sensitivity: no pets detectable
 – time on: 5min


If desired update standard settings with a screwdriver.

Step 6



Click the luminaire onto the connection plate.


Step 7



POWER
ON

Turn the power back on.

Step 8



For both maintenance and the adjustment of settings, the luminaire can gently be removed from the ceiling.

